

MR-1 CHECK OFF LIST FOR NON-CATEGORICAL COMPANIES

CRAFT TEXTILE

27220136-outlets 1 & 2

1. MONTH OF JULY 1, 2008 THRU JULY 31, 2008

- | | | | | |
|-----|--|------------------------------------|------------------------------------|--------------------------------------|
| 2. | Is Outlet # (8 digit) Correct? | <input checked="" type="radio"/> Y | N | N/A |
| 3. | Is average Total flow-gal.day stated in space provided? | <input checked="" type="radio"/> Y | N | N/A |
| 4. | Is max. Total flow-gal day stated in space provided? | <input checked="" type="radio"/> Y | N | N/A |
| 5. | Is method used to calculate water stated? | <input checked="" type="radio"/> Y | N | N/A |
| 6. | Are number of working days stated? | <input checked="" type="radio"/> Y | N | N/A |
| 7. | Are there any parameters which have exceeded PVSC Local Limits? | Y | <input checked="" type="radio"/> N | N/A |
| 8. | Is proper compliance/non-compliance statement provided? | <input checked="" type="radio"/> Y | N | N/A |
| 9. | Have correct number of samples been submitted? | <input checked="" type="radio"/> Y | N | N/A |
| 10. | Has PHC result been listed on MR-1 report? | Y | N | <input checked="" type="radio"/> N/A |
| 11. | Has sample number been reported in space provided? | <input checked="" type="radio"/> Y | N | N/A |
| 12. | Have all regulated parameters been listed on MR-1? | <input checked="" type="radio"/> Y | N | N/A |
| 13. | Has sample type been stated on MR-1? | <input checked="" type="radio"/> Y | N | N/A |
| 14. | Have all samples been taken during this reporting period? | <input checked="" type="radio"/> Y | N | N/A |
| 15. | Has NJDEPE certified lab been used? | <input checked="" type="radio"/> Y | N | N/A |
| 16. | Have analytical results been submitted on copies of Laboratory stationery? | <input checked="" type="radio"/> Y | N | N/A |
| 17. | Have results been written in space designated on MR-1? | <input checked="" type="radio"/> Y | N | N/A |
| 18. | Is correct method used to preserve samples stated on MR-1? | <input checked="" type="radio"/> Y | N | N/A |
| 19. | Has MR-1 been signed by authorized representative? | <input checked="" type="radio"/> Y | N | N/A |
| 20. | Has information been submitted on proper MR-1 form? | <input checked="" type="radio"/> Y | N | N/A |
| 21. | Remove Arsenic from report if sampling not required | Y | N | <input checked="" type="radio"/> N/A |

SEP 2008
2nd Input
Industrial Dept.

MR-1 CHECK OFF LIST FOR NON-CATEGORICAL COMPANIES

Craft Textile

27220136

First Reviewer: comments on deficiencies COMPLETEDate Reviewed 9/22/08 Date sent to user _____Date due back _____ Reviewer C.J.M.

Second review comments on deficiencies

Date Reviewed _____ Date sent to user _____

Date due back _____ Reviewer _____

Date _____ Reviewer _____

PRETREATMENT MONITORING REPORT

NAME: Craft Textile Printing Co., Inc.
 MAILING ADDRESS: P.O. Box 2761, Paterson, NJ 07509-2761
 FACILITY LOCATION: 44 Beech Street, Paterson, NJ 07501
 Category & Subpart: 9999 OUTLET # 1
 Contact Official: H.R. Casparian Telephone # 973-278-3818
 New Customer ID/Outlet ID: 27220136-1 Old Outlet Designation: 27400061



MONITORING PERIOD

START	END
7/1/2008	7/31/2008
m/d/yr	m/d/yr

Regulated Flow(gal/day)
 Total Flow (gal/day)

Average Maximum
 N/A

20830 22913


Method Used:

Gallons in less 5% evap. divided by
 production days in month (7)

Production Rate: N/A

Parameter		Mass or Concentration			# of Samples	Sample Type
		Mon Avg	Maximum	Units		
Zinc	Sample Measurement	0.0522		mg/l	1	Comp
	Permit Requirement	1.67		mg/l		
Copper	Sample Measurement	0.0256		mg/l	1	Comp
	Permit Requirement	.092/3.02		mg/l		
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					

PVSC Form MR-1 Rev: 4 6/87 P1



[Handwritten signature]

Certification of Non-Use if applicable (use additional sheets)
N/A

Compliance or non-compliance statement with compliance schedule for every parameter used:

< Local Limits:	ZN , CU	> Local Limits:	N/A
< Threshold Values	ZN , CU	> Threshold Values:	N/A


Craft Textile Printing Co., Inc., is in compliance with local limits.

Explain "Method for preserving samples:
Refrigerator until end of pumping, then nitric acid as a preservative to a pH less than 2.

I certify under penalty of law that this document and attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or the persons directly responsible for gathering the information, the information submitted is: to the best of my knowledge and belief, true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

403.6(a)(2)(ii) revised by 53 FR 40610, October 17, 1988

Signature of Principal


executive or authorized agent

H.R. Casparian-President

Name-Title


7/31/2008

Date

PVSC Form MR-1 Rev: 5 3/91 P2

PRETREATMENT MONITORING REPORT

NAME: Craft Textile Printing Co., Inc.
 MAILING ADDRESS: P.O. Box 2761, Paterson, NJ 07509-2761
 FACILITY LOCATION: 44 Beech Street, Paterson, NJ 07501
 Category & Subpart: 9999 OUTLET # 2
 Contact Official: H.R. Casparian Telephone # 973-278-3818
 New Customer ID/Outlet ID: 27220136-2 Old Outlet Designation: 27400062



MONITORING PERIOD

START	END
7/1/2008	7/31/2008
m/d/yr	m/d/yr

Average Maximum
 Regulated Flow(gal/day) N/A
 Total Flow (gal/day) 20840 22924

Method Used:

Gallons in less 5% evap. divided by
 production days in month (7)

Production Rate: N/A

Parameter		Mass or Concentration			# of Samples	Sample Type
		Mon Avg	Maximum	Units		
Zinc	Sample Measurement	0.0709		mg/l	1	Comp
	Permit Requirement	1.67		mg/l		
Copper	Sample Measurement	0.0168		mg/l	1	Comp
	Permit Requirement	.092/3.02		mg/l		
Lead	Sample Measurement	0.0036		mg/l	1	Comp
	Permit Requirement	.029/.54		mg/l		
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					
	Sample Measurement					
	Permit Requirement					

PVSC Form MR-1 Rev: 4 6/87 P1

SEP 2008
 2nd Input
 Industrial Dept.

Certification of Non-Use if applicable (use additional sheets)
N/A

Compliance or non-compliance statement with compliance schedule for every parameter used:

< Local Limits: ZN , CU , PB	> Local Limits: N/A
< Threshold Values ZN , CU , PB	> Threshold Values: N/A

Craft Textile Printing Co., Inc., is in compliance with local limits.


Explain "Method for preserving samples:

Refrigerator until end of pumping, then nitric acid as a preservative to a pH less than 2.

I certify under penalty of law that this document and attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or the persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

403.6(a)(2)(ii) revised by 53 FR 40610. October 17, 1988

Signature of Principal


executive or authorized agent

H.R. Casparian-President

Name-Title

7/31/2008

Date

PVSC Form MR-1 Rev: 5 3/91 P2



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908-789-8900 Fax: 908-789-8922

Report of Analysis

Client:	Craft Textile Printing	Date Collected:	7/1/2008
Project:	Permit Renewal 2008	Date Received:	7/1/2008
Client Sample ID:	OUTLET-1	SDG No.:	Z3519
Lab Sample ID:	Z3519-01	Matrix:	WATER
		% Solids:	0.00

CAS No.	Analyte	Conc.	Qualifier	Units	DL	Dilution	Date Prep	Date Anal.	Method
7440-50-8	Copper	25.6		ug/L	2.4	1	7/8/2008	7/9/2008	EPA SW-846 200.7
7440-66-6	Zinc	52.2		ug/L	4.8	1	7/8/2008	7/9/2008	EPA SW-846 200.7

Comments:

U = Not Detected
DL = Method Detection Limit or Instrument Detection Limit

J = Estimated Value
B = Analyte Found In Associated Method Blank
N = Spiked sample recovery not within control limits



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908-789-8900 Fax: 908-789-8922

Report of Analysis

Client:	Craft Textile Printing	Date Collected:	7/1/2008
Project:	Permit Renewal 2008	Date Received:	7/1/2008
Client Sample ID:	OUTLET-2	SDG No.:	Z3519
Lab Sample ID:	Z3519-02	Matrix:	WATER
		% Solids:	0.00

CAS No.	Analyte	Conc.	Qualifier	Units	DL	Dilution	Date Prep	Date Anal.	Method
7440-50-8	Copper	16.8		ug/L	2.4	1	7/8/2008	7/9/2008	EPA SW-846 200.7
7439-92-1	Lead	3.6	U	ug/L	3.6	1	7/8/2008	7/9/2008	EPA SW-846 200.7
7440-66-6	Zinc	70.9		ug/L	4.8	1	7/8/2008	7/9/2008	EPA SW-846 200.7

Comments:

U = Not Detected

DL = Method Detection Limit or Instrument Detection Limit

J = Estimated Value

B = Analyte Found In Associated Method Blank

N = Spiked sample recovery not within control limits



284 Sheffield Street, Mountainside, NJ 07092
(908) 789-8900 Fax (908) 789-8922
www.chemtech.net

CHEMTECH PROJECT NO

QUOTE NO

23519

COC Number

073294

CHAIN OF CUSTODY RECORD

CLIENT INFORMATION			CLIENT PROJECT INFORMATION			CLIENT BILLING INFORMATION		
REPORT TO BE SENT TO:			PROJECT NAME:			BILL TO:		
COMPANY: CRACK TEXTILE RUNNING G.			PROJECT NO.:			ADDRESS:		
ADDRESS: P.O. Box 2761			LOCATION:			CITY:		
CITY: Paterson			STATE: NJ			ZIP:		
ATTENTION: U.L. Casperian			PROJECT MANAGER:			ATTENTION:		
PHONE: 973-278-3818			e-mail:			PHONE:		
FAX: 973-523-8677			PHONE:			FAX:		
DATA TURNAROUND INFORMATION			DATA DELIVERABLE INFORMATION			ANALYSIS		
FAX: _____			RESULTS ONLY <input type="checkbox"/> USEPA CLP			<div>800 + TTS 5</div> <div>MTA - Cn</div> <div>MTA - 230</div> <div>MTA - 230</div>		
HARD COPY: _____			RESULTS + QC <input type="checkbox"/> New York State ASP "B"					
EDD: _____			New Jersey REDUCED <input type="checkbox"/> New York State ASP "A"					
PREAPPROVED TAT: <input type="checkbox"/> YES <input type="checkbox"/> NO			New Jersey CLP <input type="checkbox"/> Other _____					
STANDARD TURNAROUND TIME IS 10 BUSINESS DAYS			EDD FORMAT <input type="checkbox"/>					
PROJECT IDENTIFICATION			SAMPLE TYPE			PRESERVATIVES		
CHEMTECH SAMPLE ID			SAMPLE MATRIX			COMMENTS		
1. DUTLET #1			DATE 7/1/08			Specify Preservatives A-HCl B-HNO ₃ C-H ₂ SO ₄ D-NaOH E-ICE F-Other		
2. DUTLET #2			DATE 7/1/08					
3.								
4.								
5.								
6.								
7.								
8.								
9.								
10.								
SAMPLE CUSTODY MUST BE DOCUMENTED BELOW EACH TIME SAMPLES CHANGE POSSESSION INCLUDING COURIER DELIVERY								
RECEIVED BY: 1. J. Casperian			RECEIVED BY: 2. J. Casperian			COOLING TEMP. 50C		
DATE/TIME: 7/1/08 11AM			DATE/TIME: 7/1/08 12:15			Ice in Cooler?: YES		
RECEIVED BY: 3. J. Casperian			RECEIVED BY: 4. J. Casperian			SHIPMENT COMPLETE: YES <input type="checkbox"/> NO <input type="checkbox"/>		
DATE/TIME: 7/1/08			DATE/TIME: 7/1/08			SHIPMENT COMPLETE: YES <input type="checkbox"/> NO <input type="checkbox"/>		

NOT DOWN BOX NON USE CERTIFICATION MONITORING REPORT LOCAL LIMITS

VE: CRAFT TEXTILE

LING ADDRESS: _____

ILITY LOCATION: _____

EGORY & SUBPART _____ PERMIT # _____ OUTLET #: 27220136-2

TACT OFFICIAL: _____ TELEPHONE #: _____

ve been authorized to certify non-use for the following heavy metals:

nic _____ Lead ☒ Zinc _____

mium _____ Mercury _____



mium _____ Molybdenum _____

er ☒ Nickel _____

SAMPLE DATE

MONTH DAY YEAR

7 1 08

METER		CONCENTRATION			SAMPLE TYPE
		RESULT	THRESHOLD VALUE EXCEEDED YES OR NO	UNITS	COMP/GRAB
COPPER	Sample Measurement	<u>0.0108</u>	n	mg/l 1	Comp.
	Threshold Value	<u>0.092</u>			
LEAD	Sample Measurement	0.0010 <u>0.0036</u>	n	mg/L 1	comp.
	Threshold Value	<u>0.029</u>			
	Sample Measurement				
	Threshold Value				
	Sample Measurement				
	Threshold Value				
	Sample Measurement				  SEP 2008 2nd Input Industrial Dept.
	Threshold Value				
	Sample Measurement				
	Threshold Value				
	Sample Measurement				
	Threshold Value				
	Sample Measurement				
	Threshold Value				
	Sample Measurement				
	Threshold Value				

PVSC Form MR-3 10/96